



TYPE: Grob - G 103C Twin III SL
TCDS - No.: 869

Page: 1 of 1

Grob Aerospace
Lettenbachstr. 9
86874 Tussenhausen Mattsies
Germany
Tel. +49 8268-998-0



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1992-306/2	11.02.1993	A) Exchange of the inner main wheel fairing B) Modifications in the main wheel area	-	-
2.	1992-352	26.10.1992	Inspection of the upper pulley wheel	-	-
3.	1992-355	28.10.1992	Check and securing of the spiral pins in the brake disc of the propeller brake	-	-
4.	1992-354	28.10.1992	Exchange of the spiral pin in the spindle drive	-	-
5.	1992-367	22.10.1992	Emergency procedures! Unintended pitch change into high pitch or feathering, excessive decrease in RPM or RPM-surfing	-	-
6.	1992-388	08.12.1992	Inspection of the fuel filters	-	-
7.	1993-014	05.01.1993	Installation of a cable guide at the exhaust system	-	-
8.	1993-079	10.03.1993	Exchange of propeller switch 25 KB / Type BALLUFF	-	-
9.	1993-224	27.10.1993	Exchange of propeller flange	-	-
10.	1996-206/2	29.08.1996	Inspection and Improvement of the propeller bearing	-	-
11.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
12.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
13.	2002-066	21.03.2002	C of G Release hook - cracks at the forward attachment brackets	-	ENG / GER
14.	1996-206/3	22.08.2002	Inspection and Improvement of the propeller bearing	-	ENG / GER

