



TYPE: Grob G - 120
TCDS - No.: 1121

Page: 1 of 1

Grob Aerospace
Lettenbachstr. 9
86874 Tussenhausen Mattsies
Germany
Tel. +49 8268-998-0



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	2003-164	09.05.2003	Flight controls - operating levers with damaged ball bearing	-	ENG
2.	2003-164/2	22.05.2003	Flight controls - operating levers with damaged ball bearing - Inspection and Modification	-	ENG
3.	2003-264	12.09.2003	Flight controls - operating levers with damaged ball bearing	-	ENG
4.	2003-388	14.11.2003	Fuselage Structure – Check of Fuselage Bonding Seam	-	ENG
5.	2003-388R1	19.12.2003	Fuselage Structure – Check of Fuselage Bonding Seam	-	ENG
6.	2004-204	23.04.2004	Fuselage structure – cracks / disbanded area between vertical stabilizer main spar and adjacent vertical stabilizer skin	-	ENG
7.	2004-299	08.06.2004	Landing Gear	ENG	ENG
8.	2004-299R1	09.11.2004	Landing Gear, Extension and Retraction	-	ENG
9.	2004-514	09.12.2004	Nose Landing Gear	-	ENG
10.	2005-075	09.02.2005	Main Landing Gear - Exchange of the Main Landing Gear front and rear spherical bearings	-	ENG
11.	2004-299R2	15.03.2005	Landing Gear, Extension and Retraction	-	ENG
12.	2005-242	20.07.2005	Smoke in the cockpit due to chafing of electrical cables	-	ENG

