



TYPE: Twin Astir
TCDS - No.: 315

Grob Aerospace
Lettenbachstr. 9
86874 Tussenhausen Mattsies
Germany
Tel. +49 8268-998-0



Page: 1 of 2

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1979-258	08.05.1979	Air brake control	-	-
2.	1979-331	02.07.1979	Main control unit in fuselage center section	-	-
3.	1981-053	09.03.1981	Elevator	-	-
4.	1981-125/2	08.09.1981	Control and Elevator system	-	-
5.	1981-268	22.12.1981	Lifetime of sailplane	-	-
6.	1982-132	26.07.1982	Slide at the front pedal unit	-	-
7.	1984-058	05.04.1984	Service life of glider	-	-
8.	1985-191	12.11.1985	Aft parallel lever at the rear pedal support of the rudder control	-	-
9.	1985-222	28.10.1985	Front cockpit - airbrake operating lever	-	-
10.	1985-236	21.11.1985	Airbrakes	-	-
11.	1987-140	08.07.1987	Tow hook	-	-
12.	1987-168	02.09.1987	Rudder lever on the aft stick bulkhead	-	-
13.	1988-001	03.02.1988	Elevator push-rod III (103A-4244) or IV (103A-4694)	-	-
14.	1988-175	04.08.1988	Welded parts of control systems	-	-
15.	1988-176	15.08.1988	Inspection and exchange of both end spar spigot assemblies	-	-
16.	1989-005/2	21.03.1990	Fixing bolts of aileron connector at the distributor	-	-
17.	1992-356	28.10.1992	Inspection of the airbrake stops	-	-
18.	1992-309/2	26.02.1993	Exchange of the airbrake over-centre lever P/N 103-4123/4124	-	-
19.	1993-134	28.06.1993	Extension of operational limitations	-	-
20.	1992-190/2	04.07.1996	Extension of service life	-	-
21.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
-----	-----------	----------------	---------	---------------	------------------



WIRKK – Serwis szybowców Jerzy Biskup
34-312 Międzybrodzie Żywieckie ; Ul. Lotnicza 7,
Tel./Fax. +48 33 8662080
szd_service-jb@post.pl www.gliderservice.pl

Aktualizacja z dnia 01.07.2006



TYPE: Twin Astir
TCDS - No.: 315

Grob Aerospace
Lettenbachstr. 9
86874 Tussenhausen Mattsies
Germany
Tel. +49 8268-998-0



Page: 2 of 2

22.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
23.	1999-216	01.07.1999	Flight Controls – Inspection / Replacement of the knurled nut at the rear control stick	-	ENG
24.	1999-216/2	15.07.1999	Flight Controls – Inspection / Replacement of the knurled nut at the rear control stick	-	ENG / GER
25.	2002-067	21.03.2002	C of G Release hook - cracks at the forward attachment brackets	-	ENG / GER
26.	2003-185	30.05.2003	PLACARDS/MARKINGS (ATA: 11): Airspeed Indicator Markings and Limitation Placards	-	ENG / GER
27.	2003-231	16.07.2003	Limitations of Operation	-	ENG / GER
28.	2003-231/2	16.10.2003	Limitations of Operation	-	ENG / GER
29.	2004-002	23.01.2004	Limitations of Operation – Cancellation	-	ENG / GER
30.	2004-292	15.06.2004	Flight Controls – elevator	-	ENG / GER
31.	2003-231R3	09.11.2004	Revised Limits of Operation	-	ENG / GER
32.	2004-292R1	28.02.2005	Flight Controls – elevator	-	ENG / GER
33.	2006-057	06.03.2006	Aircraft Documentation	-	ENG / GER

