



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1971-045	08.04.1971	Aileron	-	-
2.	1972-138	13.12.1972	Improvement of starting performance at winch launching	-	-
3.	1974-070	05.06.1974	Possible longitudinal cracks at boltmaterial as an result of an material defect	-	-
4.	1974-096	05.06.1974	Aileron	-	-
5.	1977-155	09.05.1977	Horizontal all moving tail	-	-
6.	1978-162	06.07.1978	Trim	-	-
7.	1978-163	06.07.1978	Tow release cable for CG tow release	-	-
8.	1978-290	27.12.1978	Inspection hole cover on fuselage	-	-
9.	1979-044	31.01.1979	Rudder, aileron and elevator bearings	-	-
10.	1979-109	04.07.1979	Elevator drive	-	-
11.	1981-112	03.06.1981	Ground connection between control stick and C.G. release	-	-
12.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
13.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
14.	1982-184/2	02.07.1998	Increase of service life	ENG / GER	-
15.	1999-378	16.12.1999	Increase of Service Life	-	ENG / GER

