



**TYPE: DuoDiscus**  
**TCDS - No.: 396**

Page: 1 of 1

SCHEMPP - HIRTH  
Flugzeugbau GmbH  
Krebenstraße 25  
D-73230 Kirchheim Germany  
Tel. +49 7021 7298 - 0  
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	2003-246	31.07.2003	In-flight failure of wing structure at manoeuvring loads. A manufacturing defect cannot be ruled out at present. Due to the a.m. defect of airworthiness, the Luftfahrt-Bundesamt has legitimate doubts about the airworthiness of the aircraft and herewith declares the aircraft unairworthy	-	-
4.	2003-246/2	01.08.2003	Wings – bonding of spar cap to spar web	-	ENG / GER
5.	2004-084	04.02.2004	Wings – possible bonding failures between spar cap to spar web	-	ENG / GER

