



TYPE: DuoDiscus
TCDS - No.: 890

Page: 1 of 1

SCHEMPP - HIRTH
Flugzeugbau GmbH
Krebenstraße 25
D-73230 Kirchheim Germany
Tel. +49 7021 7298 - 0
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	2003-245	31.07.2003	In-flight failure of wing structure at manoeuvring loads. A manufacturing defect cannot be ruled out at present. Due to the a.m. defect of airworthiness, the Luftfahrt-Bundesamt has legitimate doubts about the airworthiness of the aircraft and herewith declares the aircraft unairworthy	-	-
4.	2003-245/2	01.08.2003	Wings – bonding of spar cap to spar web	-	ENG / GER

