



TYPE: Nimbus
TCDS - No.: 286

Page: 1 of 1

SCHEMPP - HIRTH
Flugzeugbau GmbH
Krebenstraße 25
D-73230 Kirchheim Germany
Tel. +49 7021 7298 - 0
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1987-126/3	28.09.1988	Elevator drive	-	ENG / GER
2.	1992-360/2	08.01.1993	Vertical elevator actuating rod inside the fin	-	ENG / GER
3.	1986-036/2	01.02.1994	Extension of the service time	-	ENG / GER
4.	1995-015	15.12.1994	Reinforcement of the horizontal stabilizer	-	ENG / GER
5.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
6.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
7.	1999-392	16.12.1999	Modification of engine and components – 1) Toothed belt torsion and crankshaft bearing, 2) Spindle-to-pylon attachment strut, 3) Mechanical spindle drive overload safety device, 4) Limit switch " pylon retracted", 5) Propeller brake system, 6) Fuel reserve quantity, 7), 8), and 9) Flight, Maintenance and Engine Manual	-	ENG / GER
8.	2002-357	14.11.2002	Extension of the service time	-	ENG / GER
9.	2005-239	22.07.2005	Failure of flap drive mechanism in the fuselage due to cracking of a weld joint	-	ENG / GER

