



**TYPE: ASK 21**  
**TCDS - No.: 339**

Page: 1 of 1

Alexander Schleicher  
D-36163 Poppenhausen  
(Wasserkuppe)  
Tel. +49 6658 / 89-0  
Fax. +49 6658 / 89-40



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1981-092	18.05.1981	Rudder pedals	-	-
2.	1984-002	13.01.1984	Release mechanism cable	-	-
3.	1984-032	06.03.1984	Flight Manual	-	-
4.	1984-032/2	12.06.1984	Flight Manual	-	-
5.	1984-180	25.10.1984	Wheel well	-	-
6.	1986-236	18.11.1986	Directional control-bracket assembly	-	-
7.	1988-002	18.01.1988	1. Rudder pedals; 2. Flight- and Maintenance Manual; 3. Airbrake bellcrank; 4. Rear canopy hinge	-	-
8.	1990-350	18.12.1990	Checking the parallel rocker (at the elevator actuator rod) in the fin. Exchange of this part and amendment to the Flight Manual	-	-
9.	1991-112	19.06.1991	Revision of the Flight Manual (FM)	-	-
10.	1993-186	15.09.1993	Inspection of elevator pushrod	-	-
11.	1994-026	01.02.1994	A) Amendment of the Maintenance Manual B) Inspection Program to increase the service life	-	-
12.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
13.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-

