



TYPE: Astir CS
TCDS - No.: 306

Grob Aerospace
Lettenbachstr. 9
86874 Tussenhausen Mattsies
Germany
Tel. +49 8268-998-0



Page: 1 of 1

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
2.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
3.	2001-317	11.10.2001	Flutter appearances of the elevator in the upper flight speed range - further operation of the affected sailplanes is prohibited	-	ENG / GER
4.	2001-317/2	30.11.2001	Flutter appearances of the elevator in the upper flight speed range - Reduction of V NE	-	ENG / GER
5.	2001-317/3	14.11.2002	Flutter appearances of the elevator in the upper flight speed range a) Reduction of V NE b) Increase of mass balance	-	ENG / GER
6.	2001-317/4	09.01.2003	Flutter appearances of the elevator in the upper flight speed range a) Reduction of V NE b) Increase of mass balance	-	ENG / GER
7.	2003-238	21.08.2003	Modification of the Canopy Jettison System	-	ENG / GER
8.	2003-238/2	16.10.2003	Modification of the Canopy Jettison System	-	-
9.	2004-168	23.03.2004	Horizontal stabilizer – Inspection of the vertical attachment	-	ENG / GER
10.	2004-168R1	12.06.2006	Horizontal stabilizer – Inspection of the vertical attachment	-	ENG / GER

