



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1977-257	13.09.1977	Revision of Flight Manual	-	-
2.	1979-109	04.07.1979	Elevator drive	-	-
3.	1981-112	03.06.1981	Ground connection between control stick and C.G. release	-	-
4.	1982-214	02.11.1982	Forward trim weight attachment bracket	-	-
5.	1982-215	05.11.1982	Flight and Maintenance Manual	-	-
6.	1983-118	14.06.1983	Landing gear, brake lever on Kobold hub pointing forward	-	-
7.	1988-081	29.04.1988	Increase of service life	-	-
8.	1993-083	15.03.1993	Inspection and replacement of trim weight holder	-	-
9.	1993-155	21.07.1993	Bonding of forward elevator mounting bracket in fuselage	-	-
10.	1993-156	09.08.1993	Air brake drive	-	-
11.	1993-157	09.08.1993	Landing gear drive	-	-
12.	1995-410	16.11.1995	Spring in fuselage flap drive near landing gear box	-	-
13.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
14.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
15.	2000-085	09.03.2000	Flight Controls - Jamming of the air brakes in extended position	-	ENG / GER
16.	2001-331	29.11.2001	Exchange of pages into the Flight and Maintenance Manual	-	ENG / GER

