



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1986-140/2	16.01.1987	Vibration damper installations	-	-
2.	1989-060	28.06.1989	Air brakes	-	-
3.	1991-110	18.04.1991	Pedal adjustment cable	-	-
4.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
5.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
6.	1999-266	06.07.1999	Obstruction of emergency canopy jettison	-	ENG / GER
7.	2000-082	09.03.2000	Flight Controls - Jamming of the air brakes in extended position	-	ENG / GER
8.	1999-266/2	15.03.2001	Obstruction of emergency canopy jettison and avoidance of possible injuries	-	ENG / GER
9.	2001-110	05.04.2001	Extension of the service time and Supplements of the Maintenance Manual	-	ENG / GER

