



TYPE: CIRRUS
TCDS - No.: 265

Page: 1 of 1

SCHEMPP - HIRTH
Flugzeugbau GmbH
Krebenstraße 25
D-73230 Kirchheim Germany
Tel. +49 7021 7298 - 0
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1969-136	13.11.1969	ASKUBAL-ball bearing rod ends – Replacement	-	ENG / GER
2.	1982-103	16.06.1982	1. Elevator drive 2. Tail parachute 3. Horizontal tailplane 4. Amendments to the Flight and Service Manual	-	ENG / GER
3.	1985-056	04.03.1985	Airbrake control system in the wing	-	ENG / GER
4.	1986-015	31.01.1986	Service life of glider	-	ENG / GER
5.	1993-013	22.12.1992	Control rod coupling balls on airbrake actuating lever inside the fuselage	-	ENG / GER
6.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
7.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
8.	1998-251	21.05.1998	Extension of the service life / Flight & Service Manual	GER	GER

