



TYPE: Janus CM
TCDS - No.: 809

Page: 1 of 1

SCHEMPP - HIRTH
Flugzeugbau GmbH
Krebenstraße 25
D-73230 Kirchheim Germany
Tel. +49 7021 7298 - 0
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1985-164	06.08.1985	Propeller mounting	-	ENG / GER
2.	1986-135	25.07.1986	1. Fuel supply system 2. Maintenance Manual	-	ENG / GER
3.	1990-335	29.11.1990	Elevator control system	-	ENG / GER
4.	1992-367	22.10.1992	Emergency procedures! Unintended pitch change into high pitch or feathering, excessive decrease in RPM or RPM-surfing	-	ENG / GER
5.	1992-360/2	08.01.1993	Vertical elevator actuating rod inside the fin	-	ENG / GER
6.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
7.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
8.	1999-028	11.02.1999	Extension of the service life	-	ENG / GER
9.	1999-265	06.07.1999	Horizontal Stabilizer - Mass balance on the elevator	-	ENG / GER
10.	2004-495	12.11.2004	Flight Controls – Elevator control system	-	ENG / GER
11.	2004-495R1	12.11.2004	Flight Controls – Elevator control system	-	ENG / GER

