



**TYPE: Ventus a**  
**TCDS - No.: 349**

Page: 1 of 1

SCHEMPP - HIRTH  
Flugzeugbau GmbH  
Krebenstraße 25  
D-73230 Kirchheim Germany  
Tel. +49 7021 7298 - 0  
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1987-044	25.02.1987	Flap drive inside the fuselage	-	ENG / GER
2.	1988-116	30.06.1988	Airbrakes	-	ENG / GER
3.	1992-360/2	08.01.1993	Vertical elevator actuating rod inside the fin	-	ENG / GER
4.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
5.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
6.	1999-001	11.02.1999	Extension of the service life	GER	GER
7.	2001-258	06.09.2001	Flap drive inside the fuselage	ENG / GER	ENG / GER
8.	2001-259	06.09.2001	Landing gear	ENG / GER	ENG / GER
9.	2003-280	02.10.2003	Elevator jamming due to separated balance weight	-	ENG / GER
10.	2005-136	22.04.2005	Horizontal stabilizer – Damages on the upper side of the leading edge	-	ENG / GER
11.	2005-375	28.09.2005	Fuselage / Flight Controls – Bearing of the automatic control attachment	-	ENG / GER

