



TYPE: ASW 22
TCDS - No.: 351

Alexander Schleicher
D-36163 Poppenhausen
(Wasserkuppe)
Tel. +49 6658 / 89-0
Fax. +49 6658 / 89-40



Page: 1 of 1

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
2.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
3.	2002-076	04.04.2002	Amendment of the Maintenance and Repair Manual / Extension of the service time	-	ENG / GER



WIRKK - Serwis szybowców Jerzy Biskup
34-312 Międzybrodzie Żywieckie ; Ul. Lotnicza 7,
Tel./Fax. +48 33 8662080
szd_service-jb@post.pl www.gliderservice.pl

Aktualizacja z dnia 01.07.2006