



TYPE: DG - 100
TCDS - No.: 301

DG Flugzeugbau GmbH
Otto Lilienthal Weg 2
D-76646 Bruchsal
Tel. +49 7251 3020-0
Fax +49 7251 3020-200



Page: 1 of 1

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	2004-348	02.07.2004	Rudder – lower mounting of the rudder	-	ENG / GER
4.	2004-348/2	16.09.2004	Rudder – lower mounting of the rudder	-	ENG / GER



WIRKK – Serwis szybowców Jerzy Biskup
34-312 Międzybrodzie Żywieckie ; Ul. Lotnicza 7,
Tel./Fax. +48 33 8662080
szd_service-jb@post.pl www.gliderservice.pl

Aktualizacja z dnia 01.07.2006