



**TYPE: DG - 400**  
**TCDS - No.: 826**

DG Flugzeugbau GmbH  
Otto Lilienthal Weg 2  
D-76646 Bruchsal  
Tel. +49 7251 3020-0  
Fax +49 7251 3020-200



Page: 1 of 1

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	2001-346	13.12.2001	Powerplant / rear plate of the propellermount	-	ENG / GER
4.	2004-348	02.07.2004	Rudder – lower mounting of the rudder	-	ENG / GER
5.	2004-348/2	16.09.2004	Rudder – lower mounting of the rudder	-	ENG / GER



**WIRKK – Serwis szybowców Jerzy Biskup**  
34-312 Międzybrodzie Żywieckie ; Ul. Lotnicza 7,  
Tel./Fax. +48 33 8662080  
szd\_service-jb@post.pl www.gliderservice.pl

Aktualizacja z dnia 01.07.2006