




**TYPE: Libelle H 301**

**TCDS - No.: 251**

**Page: 1 of 1**

**"Glasflügel"**  
Glasfaser – Flugzeug -  
Service GmbH  
Hofener Weg  
D-72582 Grabenstetten  
Tel. +49 7382/1032  
Fax. +49 7382/1629



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	2003-003	09.01.2003	Flight controls - Rudder gimbal drive - rear actuator arm	-	ENG
4.	2005-118	04.04.2005	Flight Controls – rudder gimbal drive – rear actuator arm	-	ENG / GER



**WIRKK – Serwis szybowców Jerzy Biskup**  
34-312 Międzybrodzie Żywieckie ; Ul. Lotnicza 7,  
Tel./Fax. +48 33 8662080  
szd\_service-jb@post.pl www.gliderservice.pl

Aktualizacja z dnia 01.07.2006