



TYPE: ASH 25
TCDS - No.: 364

Alexander Schleicher
D-36163 Poppenhausen
(Wasserkuppe)
Tel. +49 6658 / 89-0
Fax. +49 6658 / 89-40



Page: 1 of 1

No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	1998-486	14.01.1999	Increase of the service life from 6000 to 12000 hours; Inspection of elevator control linkage; additional safety device for the landing gear rear bolts and exchange of pages into the AFM and MM	-	GER



WIRKK - Serwis szybowców Jerzy Biskup
34-312 Międzybrodzie Żywieckie ; Ul. Lotnicza 7,
Tel./Fax. +48 33 8662080
szd_service-jb@post.pl www.gliderservice.pl

Aktualizacja z dnia 01.07.2006